## 1143

FIBER SENSORS

PHOTOELECTRIC SENSORS

SAFETY PRESSURE / FLOW SENSORS INDUCTIVE PROXIMITY SENSORS PARTICULAR USE SENSORS

SENSOR OPTIONS

WIRE-SAVING

WIRE-SAVING

MEASUREME SENSORS

STATIC ELECTRICITY PREVENTION DEVICES

LASER MARKERS

HUMAN MACHINE

FA COMPONENTS

MACHINE VISION SYSTEMS

UV CURING SYSTEMS

INTERFACES ENERGY CONSUMPTION VISUALIZATION COMPONENTS

PLC

SYSTEMS

SIMPLE

UNITS

LASER SENSORS

MICRO PHOTOELECTRIC SENSORS AREA SENSORS LIGHT CURTAINS /

# **Ultra-compact Digital Panel Controller** CA2 SERIES

- - General precautions..... P.1501



panasonic.net/id/pidsx/global

 Never use this product in a device for personnel protection.



In case of using devices for personnel protection, use products which meet laws and standards, such as OSHA, ANSI or IEC etc., for personnel protection applicable in each region or country.

## **Convenient functions** packed in a small body!


## **Ultra-compact**

Ultra-compact size of W48 × H24 × D65.5 mm W1.890 × H0.945 × D2.579 in. It can be mounted even in a tight space.



## Large display

Though the size is compact, the measurement display uses 4 digit, 8 mm 0.315 in letter height, red 7-segment LEDs.




## Incorporates useful functions

#### "It is troublesome to change threshold value each time..."

#### ► Auto-reference function is useful!

This function automatically adds / subtracts the changes to / from the threshold level even if there is a change in the reference pressure.

So the threshold level does not need to be changed each time.



Product can be judged Without auto-reference function as OK or NG.


Due to change in reference pressure, even an NG product is judged as an OK product.

With auto-reference function If auto-reference input is fed before pressure level judgement, when the reference pressure changes, the threshold levels are automatically changed accordingly and correct judgment is possible.


#### "I want to measure based on the measured value of the master object."

#### Zero-adjust function is useful!

This function forcibly sets the standard measured value as "0". It is convenient to measure objects based on the standard of the measurement of a master object, such as when judging variations in products.




Selection Guide Laser Displacement Magnetic Displacement Collimated Beam Metal-sheet Double-feed Detection



## Flexible scaling

The input values can be easily converted into different scales by a key operation.

Since the need to convert the displayed value is eliminated, the required information can be confirmed immediately.



Two independent outputs incorporated

low output comparison operation can be set for each output.

Further, the hysteresis for each of the outputs can be set arbitrarily.

ON

Hysteresis ON

OFF

OFF

## Various input ranges

The CA2 series is provided with 5 types of input ranges: 4 to 20 mA, 1 to 5 V,  $\pm$ 1 V,  $\pm$ 5 V and  $\pm$ 10 V. It can be used with any suitable analog sensor.



LASER MARKERS

HUMAN MACHINE ENERGY CONSUMPTION

VISUALIZATION

FA COMPONENTS

MACHINE VISION SYSTEMS

UV CURING SYSTEMS

Selection Guide
Laser Displacement
Magnetic Displacement
Collimated Beam
Digital Panel Controller
Metal-sheet Double-feed Detection

## **ORDER GUIDE**

OUT 1

OUT 1: "H", OUT 2: "L"

Singho OUT 1

2 TUO Somparative

Independent high and low output comparison operation

Hysteresis


OUT 2 threshold threshold value value

Appearance	Input range	Model No.	Output
	4 to 20 mA	CA2-T1	
	1 to 5 V	CA2-T2	
*** S S S S *** /	±1 V	CA2-T3	NPN open-collector transistor
	±5 V	CA2-T4	
	±10 V	CA2-T5	

## OUT 1: "H", OUT 2: "H"

Independent two high output comparison operation


Two independent comparative outputs (OUT 1, OUT 2) have been incorporated. High output comparison operation /





## OUT 1: "L", OUT 2: "L"

Independent two low output comparison operation



LIGHT CURTAINS / SAFETY COMPONENTS

PARTICULAR USE SENSORS

SENSOR OPTIONS

SIMPLE WIRE-SAVING UNITS

WIRE-SAVING SYSTEMS

PLC

FIBER SENSORS

## SPECIFICACTIONS

PHOTO-		Model No.	CA2-T1	CA2-T2	CA2-T3	CA2-T4	CA2-T5	
ECTRIC NSORS	Item							
MICRO PHOTO-		ply voltage		24 V D0	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	orless		
PHOTO- ECTRIC	Pow	er consumption	4 to 20 mA	1 to 5 V	2.8 W or less ±1 V	±5 V	±10 V	
AREA	S	Input range Input impedance	20 Ω	110.5 V	±1V 1N	-	TIOV	
	Indr	No. of inputs	20 12			/152		
LIGHT CURTAINS / SAFETY	og i	Input method	1 No.					
MPONENTS	Analog inputs	A/D conversion method	Single end input Successive approximation method					
ESSURE / FLOW ENSORS	4	Sampling rate			s/sec., 20 times/sec., 10 t			
DUCTIVE DXIMITY ENSORS		-adjust input	Input condition: Non-voltage contact or NPN open-collector transistor input Signal condition: Negative logic, Input time duration 10 ms or more Signal level: ON 1.5 V or less (output current: 10 mA or less) OFF Supply voltage or open Guaranteed No. of zero-adjust input usage: 10 million times or less (for zero-adjust back-up setting)					
RTICULAR USE SENSORS		DJ.) reference input EF.)						
ENSOR PTIONS	Star	t / hold input		High level (supply voltage	ge, or open): Start, Low le	vel (1.5 V or less): Hold		
SIMPLE RE-SAVING UNITS				NPN open-collector transis				
RE-SAVING SYSTEMS		nparative outputs T 1, OUT 2)	<ul> <li>Maximum sink current: 100 mA</li> <li>Applied voltage: 35 V DC or less (between comparative output and GND)</li> <li>Residual voltage: 1.3 V or less (at 100 mA sink current)</li> </ul>					
ASURE- MENT ENSORS					V or less (at 16 mA sink o	,		
STATIC CTRICITY EVENTION DEVICES		Response time	5 ms or less (when start / hold input is used at a sampling rate of 200 times/sec.)					
LASER ARKERS	Diam	Hysteresis	Variable from 1 to 3,999 digits 4 digit 7-segment red LED display (letter height: 8 mm 0.315 in)					
RKERS	Disp	-	Calastable	5 5			E time /aco	
PLC		Display refresh rate		from 20 times/sec., 10 time				
HUMAN		Display range Display accuracy	Selec	table span of 4,000 Nos. b	git) at 23 ± 5 °C 73.4 ± 41		layeu)	
MACHINE		Temperature characteristics			, , , , , , , , , , , , , , , , , , ,			
ENERGY	Setti	ing resolution	±0.5 % F.S. over 0 to +50 °C +32 to +122 °F 1 digit					
ALIZATION		shold value setting range			-9999 to +9999			
FA		Polarity indication	Red LED (lights up when the displayed value or the threshold value is negative)					
ACHINE VISION STEMS	tors	OUT 1 operation	Orange LED (Measurement mode: Lights up when OUT 1 is ON. Blinks when display is changed to OUT 1 threshold value and comparison conditions are set or when zero scale of scale setting funct				threshold value display	
UV CURING STEMS	Indicators	OUT 2 operation	Orange LED (Measurement mode: Lights up when OUT 2 is ON. Blinks when display is changed to OUT 2 threshold value display Setting mode: Blinks when OUT 2 threshold value and comparison conditions are set or when full scale of scale setting function is set					
		Auto-reference operation		Green LED (light	s up when auto-reference	function is used)	·	
	Fund	ctions	Auto-reference function, zero-adjust function, scale setting function, threshold value setting function, hysteresis setting function comparative output timer function, start / hold function, memory clear function, power supply ON-delay function etc.					
election	JCe	Ambient temperature	0 to +	55 °C +32 to +131 °F (No	dew condensation), Stora	ge: -20 to +70 °C -4 to +	158 °F	
Guide	istar	Ambient humidity		35 to 8	5 % RH, Storage: 35 to 85	5 % RH		
Laser placement	Environmental resistance	Voltage withstandability	1,500	0 V AC for one min. betwee	en all supply terminals cor	nnected together and encl	osure	
Magnetic placement	ental	Insulation resistance	100 MΩ, or m	nore, with 500 V DC megge	er between all supply term	inals connected together	and enclosure	
llimated Beam	ronm	Vibration resistance	10 to 55	5 Hz frequency, 1.5 mm 0.0	059 in amplitude in X, Y a	nd Z directions for two hou	urs each	
ital Panel Controller	Envi	Shock resistance		294 m/s <sup>2</sup> (30 G) acceler	ation in X, Y and Z direction	ons for three times each		
tal-sheet ble-feed Detection	Back-up memory		Non-volatile memory (EEPROM), Guaranteed write operations: 1,000,000 or less					
Detection	Mate	erial			Enclosure: Polycarbonate			
	Con	necting method			Terminal block connection	l		
CA2								

2) If this product is to be used as a CE (European standard EMC Directive) approved product, make sure to connect ferrite clamps, with one loop,

on all the connection cables, as shown in the right figure. Also, make sure not to exceed 10 m 32.808 ft in cable length.




<Recommended ferrite clamp> Noise filter for single line ZCAT3035-1330 [Manufactured by TDK Corporation]

## I/O CIRCUIT AND WIRING DIAGRAMS


#### Input circuit diagram

### IN, ST / HOLD, 0-ADJ. / A-REF.



### Output circuit diagram


#### OUT1, OUT2



Symbols ... D: Reverse supply polarity protection diode ZD1, ZD2: Surge absorption zener diode Tr1, Tr2: NPN output transistor


## DIMENSIONS (Unit: mm in)





Note: COM. (0 V) is internally connected to GND.

#### \* 1



ON: 1.5 V or less (output current 10 mA or less) OFF: Supply voltage, or open

#### Digital panel controller



1146

FIBER SENSORS

LASER SENSORS

PHOTO-ELECTRIC SENSORS

MICRO PHOTO-ELECTRIC SENSORS

AREA SENSORS

LIGHT CURTAINS / SAFETY COMPONENTS

PRESSURE / FLOW SENSORS

INDUCTIVE PROXIMITY SENSORS

PARTICULAR USE SENSORS

SENSOR OPTIONS

SIMPLE WIRE-SAVING UNITS

WIRE-SAVING SYSTEMS

STATIC ELECTRICITY PREVENTION

LASER MARKERS

PLC


HUMAN MACHINE INTERFACES

ENERGY CONSUMPTION VISUALIZATION COMPONENTS

FA COMPONENTS MACHINE


Selection Guide
Laser Displacement
Magnetic Displacement
Collimated Beam
Digital Panel Controller
Metal-sheet Double-feed Detection

CA2



## Panel cut-out dimensions

The CAD data in the dimensions can be downloaded from our website.



Note: The panel thickness should be 0.5 to 4 mm 0.020 to 0.157 in.